



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Maralex Resources, Inc
Received

OIL CONS. DIV DIST. 3

SEP 09 2015

AUG 10 2015

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-4-15 Operator MARALEX RES API #30-0 45-29983

Property Name TRADING POST Well No 26#1 Location: Unit Section Township Range

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>	<u>NA</u>	
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min	<u>0</u>		<u>0</u>		
25 min	<u>0</u>		<u>0</u>		
30 min	<u>0</u>		<u>0</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>0</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE

REMARKS:

By BOB SPENCER

Witness

PUMPER

(Position)

E-mail address maralex-tech@gmail.com