



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III3district.htm](http://emrdd.state.nm.us/ocd/District%20III3district.htm)

OIL CONS. DIV DIST. 3

SEP 09 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-25-2015 Operator MARALEX RES, INC. API #30-0 45-30125

Property Name Training Post Well No 23-2 Location: Unit Section Township Range

Well Status (Shut-In or Producing) Initial PSI: Tubing 30 Intermediate Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min			30		
10 min			30		
15 min			30		
20 min			30		
25 min			30		
30 min			30		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By BOB SPENCER

Witness [Signature]

PUMPER
(Position)

E-mail address maralextech@gmail.com