



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III3distr.htm](http://emnrd.state.nm.us/ocd/District%20III3distr.htm)

Maralex Resources, Inc

Received

OIL CONS. DIV DIST. 3

SEP 09 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 10 2015

Ignacio

Colorado

Date of Test 8-4-15 Operator MARALEX RES API #30-0 45-31279

Property Name TRADING POST Well No 26-3 Location: Unit Section Township Range

Well Status (Shut-In or Producing) Initial PSI: Tubing 43 Intermediate Casing 51 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>51</u>		
10 min	<u>0</u>		<u>51</u>		
15 min	<u>0</u>		<u>51</u>		
20 min	<u>0</u>		<u>51</u>		
25 min	<u>0</u>		<u>51</u>		
30 min	<u>0</u>		<u>51</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>0</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By BOB SPENCER

Witness

PAMPER

(Position)

E-mail address maralextech@gmail.com