



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

SEP 09 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

<http://emnrd.state.nm.us/ocd/District/3/district.htm>

Received
AUG 17 2015
10:00 AM
Colorado

Date of Test 8-11-15 Operator MARALEX RES. API #30-0 45-33874

Property Name TRADING POST Well No. 35-1 Location: Unit ___ Section ___ Township ___ Range ___

Well Status (Shut-In or Producing) Initial PSI: Tubing 30 Intermediate ___ Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>35</u>	<u>N/A</u>	
10 min	<u>0</u>		<u>35</u>	<u> </u>	
15 min	<u>0</u>		<u>35</u>	<u> </u>	
20 min	<u>0</u>		<u>35</u>	<u> </u>	
25 min	<u>0</u>		<u>35</u>	<u> </u>	
30 min	<u>0</u>		<u>35</u>	<u>↓</u>	

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>0</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE ___

REMARKS:

By BOB SPENCER

Witness ___

PUMPER

(Position)

E-mail address maralex-tech@gmail.com