



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

SEP 14 2015

(submit 1 copy to above address)

Date of Test 9-14-15 Operator Burlington Res API #30-0 39-23501
Property Name SS 30-64 SW 1/4 Well No. 1124 Location: Unit 26 Section 26 Township 30 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 66 Intermediate 2 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	1.7	100	0	0
10 min	0	1.7	0	0	0
15 min	0	1.7	0	0	0
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - Nothing when opened -
Int. Med light to light blow at 1 min to Sealy. Light
at 1.5 min to vapors at 2 min. Dead at 4 min

By Boyd Small

Witness

Monica Kuehling
Int - Nothing when opened after
5 min shut-in

(Position)

E-mail address