



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3ddistrict.htm](http://emnrd.state.nm.us/ocd/District%20III/3ddistrict.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

SEP 17 2015

(submit 1 copy to above address)

Date of Test 8-31-15 Operator Pro Management API #30-0 45-24076

Property Name Nickles Well No. 1M Location: Unit 0 Section 11 Township 31 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 228 Intermediate Casing 228 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>228</u>		
10 min	<u>1</u>		<u>228</u>		
15 min	<u>1</u>		<u>228</u>		
20 min	<u>2</u>		<u>228</u>		
25 min	<u>2</u>		<u>228</u>		
30 min	<u>2</u>		<u>228</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	☒
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Mark West

Witness

Pumper
(Position)

E-mail address