



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test Sept 15 2005 Operator ELM RIDGE API #30-0 45-28877  
Property Name W. BIST. Co. 125 Well No. 25 Location: Unit SS Section 25 Township 25N Range 13W  
Well Status (Shut-In or Producing) open Tubing 12 pss Intermediate open Casing 12 pss Bradenhead 3 pss

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes				Steady Flow	
10 minutes				Surges	
15 minutes	<u>3 pss</u>		<u>12 pss</u>	Down to Nothing <u>X</u>	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas <u>X</u>	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 pss INTERMEDIATE \_\_\_\_\_

REMARKS:



One 1" B.H. Valve left closed

B.H. HAD 3 pss Bled to 0 pss in 5 minutes

By CEC DURHAM

Witness \_\_\_\_\_

Plumber  
(Position)

E-mail address \_\_\_\_\_