

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test Sept 15, 'DUNS Opera	or EZM N 19 @ API #30-0 45-28140
	18-1 Location: Unit Section /8 Township 25 NRange /2 W
Well Status (Shut-In or Producing) Tubing_1	Pantermediate Casing 11 ps Bradenhead of 35
OPEN BRADENHEAD AND INTERMEDIAT	E TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CAS	BRADENHEAD INTERMEDIATE FLOWED FLOWED
5 minutes	Steady Flow
10 minutes	Surges
15 minutes O pro-	Down to Nothing
20 minutes	Nothing A
25 minutes	Gas
30 minutes	Gas & Water
	Water
If bradenhead flowed water, check all of the descript	ions that apply below:
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE	
REMARKS: HAS ONE 1" B.H. Valve jest Closed	
	10,10,30,30
By (EC.) Dar Ham	Witness
By CECIDARHAM  Pamper	NOV 2008
(Position)	- CONS. ON. 3
E-mail address	
<i>∞</i> .*	20 C + C 1.