



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.enmrd.state.nm.us/ocd/District3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 11-10-05 Operator Maralex Resources, Inc API # 30-0 45-31908

Property Name Cecil Cast Well No. 2A Location: Unit E Section 19 Township 30N Range 11W

Well Status (Shut-In or Producing) Tubing 0 Intermediate N/A Casing 100 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	0	N/A	100	Steady Flow <u>None</u>	N/A
10 minutes	0	N/A	100	Surges <u>None</u>	N/A
15 minutes	0	N/A	100	Down to Nothing <u>None</u>	N/A
20 minutes	0	N/A	100	Nothing <u>✓</u>	N/A
25 minutes	0	N/A	100	Gas <u>None</u>	N/A
30 minutes	0	N/A	100	Gas & Water <u>None</u>	N/A
				Water <u>None</u>	N/A

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By Steven R Szumlinski

Witness _____

Pumper
(Position)

E-mail address _____

