

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

2005 APR 13 AM 11 31

RECEIVED

FARMINGTON NM

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Dugan Production Corp.

3. Address and Telephone No.

P.O. Box 420, Farmington, NM 87499 (505) 325 - 1821

Location of Well (Footage, Sec., T., R., M., or Survey Description)

2000' FNL & 1980' FWL (Unit F)
SE/4 NW/4, Sec. 3, T25N, R13W

5. Lease Designation and Serial No.

SF 078156 A

6. If Indian, Allotted or Tribe Name

7. If Unit or CA, Agreement Designation

NMNM89398

8. Well Name and No.

Cisco Com #90S

9. API Well No.

30 045 31345

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal

11. County or Parish, State

San Juan, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Reserve pit closure
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The reserve pit liner was intact. Completion fluids were produced into the reserve pit during testing, however all fluid was removed for disposal prior to covering pit. On 1-10-05, the reserve pit was fairly dry. The pit liner was cut at the mud line and the recovered liner disposed of at Waste Management's Crouch Mesa landfill. The pit area was covered with stockpiled top soil to a depth of at least 3'. The surface was contoured and will be seeded in early spring. The pit center is 21' N 78° E from wellhead.

FARMINGTON FIELD OFFICE
BY 1527

14. I hereby certify that the foregoing is true and correct

Signed John D. Roe Title Engineering Manager Date 04/12/2005

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____

Conditions of approval, if any:

APPROVED