1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

State of New Mexico Energy Minerals and Natural Resources

Form C-144 June 1, 2004

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe

Pit or Below-Grade Tank Registration or Closure


	ered by a "general plan"? Yes No								
(Wfs と つろいえを) Type of action: Registration of a pit or below	v-grade tank	<u> </u>							
Operator: GENERAL MINERALS CORP Telephone:	e-mail address:								
Address: 4133 N LINCOLN BLVD OKLAHOMA CITY, OK 73105									
Facility or well name: CHARLES #001 API #: 30-045-	$\frac{21869}{\text{U/L or Qtr/Qtr}} \qquad \frac{M}{\text{M}} \text{SEC}$	<u>24</u> T <u>28N</u> R <u>11W</u>							
County: SAN JUAN Latitude 36.64357 Longitude -107.96083 NAD: 1927 ✓ 1983 □ Surface Owner: Federal ✓ State □ Private □ Indian □									
Pit Type: Drilling □ Production ✓ Disposal □	Below-grade tank Volume: bbl Type of fluid:								
Workover Emergency	Construction Material:								
Lined Unlined	Double-walled, with leak detection? Yes 🗐 If not, exp	explain why not.							
Liner Type: Synthetic Thickness mil Clay Pit Volume 120 bbl									
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) <u>0</u> (0 points)							
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) <u>0</u>							
Distance to surface water: (Horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet to 1,000 feet Greater than 1,000 feet	(20 points) (10 points) <u>0</u> (0 points)							
	Ranking Score (TOTAL POINTS):	<u>0</u>							
If this is a pit closure: (1)Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if your are burying in place) onsite ✓ offsite ☐ If offsite, name of facility									
action taken including remediation start date and end date. (4)Groundwater encountered: No Yes If yes, show depth below ground surface ft. and attach sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results are sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results are sample results. (5)Attach soil sample results and a diagram of sample locations and excavations in the sample results are sample results. (6)Attach soil sample results are sample results and a diagram of sample results are sample results. (6)Attach soil sample results and a diagram of sample results are sample results. (7)Attach soil sample results are sample results are sample results are sample results. (7)Attach soil sample results are sample results are sample results are sample results are sample results. (8)Attach soil sample results are sample results. (8)Attach soil sample results are sample results are sample re									
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade									
tank has been/will be constructed or closed according to NMOCD guidelines, a general permit, or an (attached) alternative OCD-approved plan									
Date:9/18/05									
Your certification and NMOCD approval of this application/closure does not relieve the operations.	ve the operator of liablility should the contents of the pit or ta	nk contaminate ground water ral, state, or local laws and/or							
Approval: OFFUTY OR & GAS INSPECTOR, DIST.	Very Faut	OCT 1 2 20							

ADDENDUM TO OCD FORM C-144


Operator: GENERAL MINERALS CORP

Well Name: CHARLES #001 Meter: 34431

Facility Diagram:



Sampling Diagram:



Pit Dimensions

Length 15 Ft.

Width 15 Ft.

Depth 3 Ft.

Location of Pit Center

Latitude <u>36.64347</u>

Longitude <u>-107.96061</u>

(NAD 1927)

Pit ID

API 30-045-21869

<u>344311</u>

Pit Type

<u>Other</u>

Date Closure Started: <u>6/18/04</u>

Closure Method:

Pushed In

Date Closure Completed: 6/18/04

Bedrock Encountered?

Cubic Yards Excavated:

Vertical Extent of Equipment Reached ? \Box

Description Of Closure Action:

The pit was assessed and sampled in accordance with NMOCD guidelines. Based on assessment findings, the pit was backfilled.

Pit Closure Sampling:

Sample ID

Sample Date Head Space

BTEX Total

(mg/kg)

Benzene (mg/kg) Purpose

TPH

DRO

(mg/kg)

190

ose L

Location Depth

3

103805FEB04

2/5/04

0

0

ASSESS

Flr



606814994

Lab Sample No:

Pace Analytical Services, Inc. 9608 Loiret Blvd. Lenexa, KS 66219

> Phone: 913.599.5665 Fax: 913.599.1759

Lab Project Number: 6079093

Client Project ID: NM Pit Program

CTIENT HOJECT ID. WHATE HOGIC

Project Sample Number: 6079093-008

Date Collected: 02/05/04 10:38
Date Received: 02/10/04 09:30

Client Sample ID: 103805FEB04		Matrix: Soil			i	Date Received: 02/10/04 09:30			
Parameters	ో Results	Units	Report Limit	DF	Anal yzed	Ву	CAS No.	Qua1	RegLmt
GC Semivolatiles									
Total Extractable Hydrocarbons	Prep/Method:	OA2 / OA2							
Mineral Spirits	ND	mg/kg	11.	1.1 02/1	2/04 22:54	RMN1			
Jet Fuel	ND	mg/kg	. 11.	1.1 02/1	2/04 22:54	RMN1			
Kerosene	ND	mg/kg	11.	1.1 02/1	2/04 22:54	RMN1			
Diesel Fuel	ND	mg/kg	11.	1.1 02/1	2/04 22:54	RMN1	68334-30-5		
Fuel 011	ND	mg/kg	11.	1.1 02/1	2/04 22:54	RMN1	68334-30-5		
Motor 0il	190	mg/kg	11.	1.1 02/1	2/04 22:54	RMN1			
n-Tetracosane (S)	118	*		1.0 02/1	2/04 22:54	RMN1	646-31-1		
p-Terphenyl (S)	104	*		1.0 02/1	2/04 22:54	RMN1	92-94-4		
Date Extracted	02/12/04			02/1	2/04				
Organics Prep							•		
Percent Moisture	Method: SM 2	2540G							
Percent Moisture	6.7	*		1.0 02/1	.2/04	DPB			
GC Volatiles									
Aromatic Volatile Organics	Prep/Method:	EPA 5030 M	edium Soil / E	PA 8021					
Benzene	ND	ug/kg	54.	1.1 02/1	6/04 19:00	DCKI	71-43-2		
Ethylbenzene	ND	ug/kg	54.	1.1 02/1	6/04 19:00	DCKI	100-41-4		
Toluene	ND	ug/kg	54.	1.1 02/1	6/04 19:00	DCKI	108-88-3		
Xylene (Total)	ND	ug/kg	140	1.1 02/1	.6/04 19:00	DCKI	1330-20-7		
a,a,a-Trifluorotoluene (S)	101	*		1.0 02/1	.6/04 19:00	DCKI	98-08-8		

Date: 02/17/04

Page: 8 of 19

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc.

