

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

30-043-20806
Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Gary-Williams Oil Producer, Inc.

3. ADDRESS OF OPERATOR
115 Inverness Drive East, Englewood, CO 80112-5116

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
660' FSL and 660' FWL (SW SW) Section 24-T20N-R3W

5. LEASE DESIGNATION AND SERIAL NO.
NM-27432

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
N/A

7. UNIT AGREEMENT NAME
N/A

8. FARM OR LEASE NAME
San Isidro 24

9. WELL NO.
13

10. FIELD AND POOL, OR WILDCAT
Rio Puerco Mancos

11. SEC., T., R., M., OR B.L. AND
SURVEY OR AREA
SW SW 24-T20N-R3W

12. COUNTY OR PARISH
Sandoval

13. STATE
NM

14. PERMIT NO.

15. ELEVATIONS (Show whether SP, ST, OR STA.)
6944' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACURE TREAT	<input type="checkbox"/>	FRACURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETS	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugging Report. MIRU Big A Well Service. RIH with 2-3/8" tbg open ended.
Tag cement @ 1912.60 KB. (Note: 200 sx placed across Menefee perforations on 9-20-86).

RU B J Titan. Circ hole with 95 bbl of drlg mud recovered from pit (est. 12 ppg 60-70 VIS). POOH to 840' KB. Spot 25 sx (29.5 cu ft) plug across top of Chacra. POOH to 450' KB. Spot 85 sx (100.30 cu ft) plug from 450' to surface to protect Picture Cliff and Fruitland formation. Circulated estimated 10 sx to pit. Full returns while cementing plugging operations. Plugging operations witnessed by Rio Puerco BLM representative. Weld on dry hole marker. Well bore permanently P & A'd 4-21-87.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED Nancy McDonald

TITLE Compliance Administrator

DATE 4/22/87

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED
APR 27 1987

OIL CON. DIV.

*See Instructions on Reverse Side. 3

NMOCG

APPROVED

DATE 4/22/87

APR 24 1987

AREA MANAGER
FARMINGTON RESOURCE AREA