

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emmd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12 - 30 - 200 5	Operator FL	1 RIDGE	API #30-0 식5·	28162
Property Name Sours BLAND CED Well No. 23-2 Location: Unit N Section 23 Township 24 PRange 8 W				
Well Status (Shut-In) or Producing) Tubing O Intermediate Casing O Bradenhead O				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURES: TIME BRADENHEAD INTERMEDIA	TE CASING		BRADENHEAD FLOWED	INTERMEDIATI FLOWED
5 minutes O	0	Steady Flow		
10 minutes	0	Surges		
15 minutes	0	Down to Nothin	ng	
20 minutes		Nothing		
25 minutes		Gas		
30 minutes		Gas & Water_		
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK FEB 2000				
CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE REMARKS: SALTY SULFUR BLACK FEB 2006 ON CONS. Day. REMARKS: REMARKS:				
REMARKS: San Juan Co.				
			7. D.	المراجعة الم
	na saamuulun suuru, gaallasalaja 12 – sahkiin saatiikkiin kunistiili tuud kasta kaliitiikkii	والمستقدمة		
By Jason Menz	W	itness		
Sease Op. (Position)				
E-mail address				