

## submitted in lieu of Form 3160-5 **UNITED STATES**

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

|                   | BUREAU OF EARLY MINISTERIE   | /        |   |  |
|-------------------|--|----------|---|--|
|                   | Sundry Notices and Reports on Wells 7005 FEB 21 / FM 3   | 44       |   |  |
| 1.                | Type of Well GAS  RECEIVED 070 FARMINGTON  | 5.<br>6. | Lease Number<br>NMSF-079382<br>If Indian, All. or<br>Tribe Name |  |
| 2                 | Name of Operator   | 7.       | Unit Agreement Name   |  |
| 2.<br>            | BURLINGTON RESOURCES OIL & GAS COMPANY LP  | - 8.     | San Juan 30-6 Unit<br>Well Name & Number                        |  |
| σ.                | PO Box 4289, Farmington, NM 87499 (505) 326-9700  PO Box 4289, Farmington, NM 87499 (505) 326-9700   | 9.       | San Juan 30-6 Unit #95B<br>API Well No.                         |  |
| -<br>4.           | Location of Well, Footage, Sec., T, R, M   | -        | 30-039- 29807   |  |
| ٦.                | Sec., TN, RW, NMPM   | 10.      | Field and Pool  |  |
| _                 | Unit C (NENW) 750' FNL & 2170' FWL, Sec. 26, T30N, R7W NMPM  |          | Blanco Mesaverde/ Basin Dakota                                  |  |
| )                 | UIII C (NENW) 750° FNL & 2170° FWL, Sec. 20, 130N, R/W NWIFW   | 11.      | County and State<br>Rio Arriba Co., NM                          |  |
| 12.               | CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, O' Type of Submission Type of Action  X Notice of Intent Abandonment X Change of Plans Other Recompletion New Construction  Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection |          | DATA  |  |
| 13.               | Describe Proposed or Completed Operations  |          |   |  |
|                   | ne access road was moved to 550' on the NW corner to avoid grassland. To as 750' on the SE corner.   | he for   | mer access road   |  |
|                   | ned Amanda Sandoval Title Regulator  | ory Assi | stant III Date <u>2/16/06</u>                                   |  |
| AP<br>CO<br>Title | PROVED BY  Title   Bearth Chief  NDITION OF APPROVAL if any:  18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of mited States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.                       |          | Date 2/22/06  |  |



Note: Contractor should call One-Call for location of any marked or unmarked puried pipelines or cables on well pad and/or access road at least two (2) working days prior to construction



## Directions from the Intersection of US Hwy 550 & State Hwy 64 in Bloomfield, NM to Burlington Resources Oil & Gas Company San Juan 30-6 Unit #95B 750' FNL & 2170' FWL, Section 26, T30N, R7W, N.M.P.M., Rio Arriba County, NM

From the intersection of US Hwy 550 & State Hwy 64 in Bloomfield, NM, travel Easterly on State Hwy 64 for 24.0 miles to State Highway 539;

Go left (North-easterly) on State Highway 539 for 3.9 miles;

Go right (North-easterly) on DeLasso Loos Road for 6.0 miles to fork in road;

Go right (South-westerly) for 0.3 miles to fork in road;

Go left which is straight (South-easterly) for 0.3 miles to fork in road;

Go right (South-westerly) for 0.2 miles to new access on left-hand side of existing roadway which continues for 550' to staked location.