

Deviation Report

Name of Company

Burlington Resources Oil & Gas Company

Address

P.O. Box 4289, Farmington, NM 87499

Lease Name and Number (API Number)

CULPEPPER MARTIN #1M (30-045-33083)

Location

975 FNL 670 FEL

Sec. Twn. Rge.

31-032N-012W

Pool and Formation

BLANCO MESAVERDE/BASIN DAKOTA

County

SAN JUAN

State

NEW MEXICO


(OH)

Depth (ft)**Deviation (degrees)**

100	1.00
200	1.00
715	1.00
1,214	1.00
1,712	1.00
2,210	1.00
2,706	1.00
3,204	1.00
3,700	1.00
4,110	1.00
6,970	3.00

Air Hammer Used? YES / NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.



Subscribed and sworn to before me this 6th day of March, 2006.



Notary Public in and for San Juan County, New Mexico

My commission expires March 31, 2006.



