



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III3distric.htm](http://emnrd.state.nm.us/ocd/District%20III3distric.htm)

OIL CONS. DIV DIST. 3

OCT 02 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-2-15 Operator Elm Ridge API #30-0 45-05486  
Property Name CBU WI Well No. 63 Location: Unit E Section 8 Township 25 Range 12  
Well Status(Shut-In or Producing) Initial PSI: Tubing 12 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	0	0	0
10 min	0	0	0	0	0
15 min	0	0	0	0	0
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	/	/
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH - Nothing when opened. Nothing when opened after 5 min shut-in - Int - Nothing when opened. Nothing when opened after 5 min shut-in

By Jack Bingham

Witness Monica Cuhling

(Position)

E-mail address \_\_\_\_\_