



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-15-15 Operator Zuley Torres API #30-0 45-05963
Property Name Huamantla Well No. 91 Location: Unit 12 Section 26 Township 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 118 Intermediate Casing 313 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		314		
10 min	0		315		
15 min	0		316		
20 min	0		316		
25 min	0		317		
30 min	0		317		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	/
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
OCT 15 2015

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 118

REMARKS:

long puff when opened.

Nothing when opened after 5 min shut in

By [Signature]

Witness [Signature]

(Position)

E-mail address