



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

OIL CONS. DIV DIST. 3

OCT 14 2015

Date of Test 5/28/15 Operator BP America Production Company API # 3004508263

Property Name GCU COM C 144-DK Location: Unit L Section 16 Township 29 Range 12
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 60 Intermediate N/A Casing 65 Bradenhead 32

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate Flowed Flowed	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>P</u>	<u>38</u>				Steady Flow	
10 minutes	<u>W</u>	<u>33</u>				Surges	
15 minutes	<u>W</u>	<u>30</u>				Down to Nothing	
20 minutes	<u>W</u>	<u>30</u>				No Flow	
25 minutes	<u>W</u>	<u>28</u>				Gas	
30 minutes	<u>W</u>	<u>25</u>				Gas and Water	
5 minute SI	<u>3</u>	<u>27</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 3 Intermediate N/A

REMARKS:

BH had a puff to a whisper in 2 sec. Blew from 1" valve
Casing dropped due to plunger arrival

Sample Taken BH bottle was #22 Prod. Casing was #11

By [Signature] Witness _____

(Position)