



Gallegos Canyon Unit Com C 144

Dakota

API # 30-045-08263

T-29N, R-12-W, Sec. 16
San Juan County, New Mexico

History

Spud Date: 1/5/1964

Completion Date: 1/26/1964

1/2/1992: Bradenhead repair. Perf'd at 800'.

Pumped 200 sx. Circulated to surface.

1/30/2008: Changed out Master Valve.

12/14/10: Wirelined. Retrieved broken plunger @ 6040'

"sticky". Retrieved stop (worn). Tagged solid at 6085'.

did not retrieve sample. Impression block showed

cross pin at 6085'. Reran new slip stop at 6054'.

Formation Tops

PC	1570
Mesaverde	3113
Manco Sh	4316
Gallup	5216
Dakota	6144

Dakota Perforations

3071-6082'

frac w/ 25,700 gals wtr & 20,000# snd.

3154-6174'

frac w/ 14,700 gals wtr & 11,300# snd.

Refrac'd w/ 36,300 gals wtr & 33,000# snd.

