

(Position)

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

OIL CONS. DIV DIST. 3

(Submit 2 copies to above address) OCT 1 4 2015 **Date of Test** Operator **BP America Production Company** API# 3004524179 8/17/15 GCU COM 094E-GP Location: Unit A Section 23 Township Range 13 **Property Name** (Well Name and Number) Pressure (Shut-in or Preducing) Tubing Intermediate Bradenhead 105 Casing OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH Bradenhead Intermediate Bradenhead Intermediate BH Casing Intermediate Intermediate Casing Flowed Flowed Time Monitor Monitor Monitor Blowdown Blowdown Steady Flow 5 minutes Surges 10 minutes 49 Down to Nothing 15 minutes 49 No Flow 20 minutes Gas 25 minutes Gas and Water 30 minutes Water 5 minute SI 49 If bradenhead flowed water, check all of the descriptions that apply below: Sulfur Black Clear Fresh Salty Intermediate 5 Minute Shut-in Bradenhead REMARKS: I" value. BH blew down to nothing men tell Witness