



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DEC 17 2015

Date of Test 17 DEC 2015 Operator WPX API #30-0 7A

Property Name ROSA SWD Well No. 1 Location: Unit Section 23 Township 31 Range 4

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 1 Casing 0 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>1</u>	<u>1</u>	<u>0</u>	<u>1</u>	<u>0</u>
10 min	<u>1</u>	<u>1</u>	<u>0</u>	<u>1</u>	<u>0</u>
15 min	<u>1</u>	<u>1</u>	<u>0</u>	<u>1</u>	<u>0</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	<u>X</u>
Nothing		
Gas	<u>X</u>	<u>X</u>
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

OPENED THE BRADENHEAD AND IT BLEW DOWN
TO NOTHING IN LESS THAN 1 SECOND. OPENED THE INTERMEDIATE
AND IT BLEW DOWN TO NOTHING IN LESS THAN 1 SECOND

By Kenton Schwettman
Lead Tech
(Position)

Witness John Qum

E-mail address Kenton.schwettman@wpxenergy.com