



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

DEC 18 2015

(submit 1 copy to above address)

Date of Test 12/1/15 Operator BP API #30-0 4524839

Property Name BLU Well No. 189E Location: Unit K Section 36 Township 29 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate - Casing - Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS		
	Bradenhead	INTERM		BRADENHEAD	INTERMEDIATE	
	BH	Int	Csg			
TIME						
5 min	<u>0</u>		<u>0</u>			
10 min	<u>0</u>		<u>0</u>			
15 min	<u>0</u>		<u>0</u>			
20 min						
25 min						
30 min						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

Blew from 1" valve. Btl had no flow. Slim hole well.
Used tubing in place of casing

By

[Signature]

Witness

(Position)

E-mail address
