

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

JAN 21 2016

Submit 1 Copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

Form C-141  
Revised August 8, 2011

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company <b>ConocoPhillips Company</b>	Contact <b>Lisa Hunter</b>
Address <b>3401 East 30<sup>th</sup> St, Farmington, NM</b>	Telephone No. <b>(505) 326-9786</b>
Facility Name: <b>San Juan 28-7 Unit 252E</b>	Facility Type: <b>Gas Well</b>

Surface Owner <b>Federal</b>	Mineral Owner <b>Federal</b>	API No. <b>3003923748</b>
------------------------------	------------------------------	---------------------------

#### LOCATION OF RELEASE

Unit Letter <b>N</b>	Section <b>32</b>	Township <b>T28N</b>	Range <b>R07W</b>	Feet from the <b>1135</b>	North/South Line <b>South</b>	Feet from the <b>1565</b>	East/West Line <b>West</b>	County <b>Rio Arriba</b>
-------------------------	----------------------	-------------------------	----------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude 36.61375 Longitude -107.59957

#### NATURE OF RELEASE

Type of Release <b>Natural Gas</b>	Volume of Release <b>73mcf</b>	Volume Recovered <b>0</b>
Source of Release <b>Connection of Lubricator - Corrosion</b>	Date and Hour of Occurrence	Date and Hour of Discovery <b>11/23/15 @ 9:00 am</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <b>N/A</b>	
By Whom? <b>N/A</b>	Date and Hour <b>N/A</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully.\*

**N/A**



Describe Cause of Problem and Remedial Action Taken.\*

**Small leak due to corrosion was discovered at the threads in 1/2" nipple on lubricator releasing 73 mcf natural gas into atmosphere. Wellhead isolated, blew down and replaced leaking connection. Returned well to production.**

Describe Area Affected and Cleanup Action Taken.\*

**No further remediation required.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
	Approved by Environmental Specialist: 	
Printed Name: <b>Lisa Hunter</b>	Approval Date: <b>1/21/2016</b>	Expiration Date:
Title: <b>Field Environmental Specialist</b>	Conditions of Approval:	
E-mail Address: <b>Lisa.Hunter@cop.com</b>	Attached <input type="checkbox"/>	
Date: <b>November 28, 2015</b> Phone: <b>(505) 326-9786</b>		

\* Attach Additional Sheets If Necessary

**NUF 1602154261**