

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OIL CONS. DIV DIST. 3

JAN 14 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Bobby Spearman	
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 324-6131	
Facility Name: Quinn #6	Facility Type: Gas well	
Surface Owner Fee	Mineral Owner BLM	API No. 300451060

LOCATION OF RELEASE

Unit Letter A	Section 20	Township 31N	Range 8W	Feet from the 990	North/South Line North	Feet from the 990	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	--------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	---------------------------

Latitude **36.88754** Longitude **-107.69275**

NATURE OF RELEASE

Type of Release Condensate	Volume of Release 23bbls	Volume Recovered 22bbls
Source of Release Production tank	Date and Hour of Occurrence 1-7-16 10:30a	Date and Hour of Discovery 1-7-16 10:30a
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Production tank developed a hole due to corrosion spilling 23 bbl of oil, well was shut in and the remaining oil in the tank was pulled and transferred. Crew was able to recover 22bbls of oil.

Describe Area Affected and Cleanup Action Taken.*

Spill was contained within the berm area of the location. Crews removed frozen soil and oil and hauled to disposal. Due to frozen ground and snow levels ConocoPhillips will perform soil sampling as soon as possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Spearman	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Environmental Specialist	Approval Date: 1/22/2016	Expiration Date:
E-mail Address: Robert.E.Spearman@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1-12-16 Phone: 505-324-6131	Sample For TPH, BTEX, Chlorides NOF1600837175	

* Attach Additional Sheets If Necessary

①