

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

JAN 25 2016

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: BP	Contact: Steve Moskal
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497
Facility Name: Gallegos Canyon Unit 159	Facility Type: Natural gas well
Surface Owner: Tribal	Mineral Owner: Tribal
API No. 3004507040	

**LOCATION OF RELEASE**

Unit Letter F	Section 31	Township 28N	Range 12W	Feet from the 1,765	North/South Line North	Feet from the 1,585	East/West Line West	County: San Juan
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	------------------

Latitude 36.62114° Longitude -108.15616°

**NATURE OF RELEASE**



Type of Release: produced water	Volume of Release: 6.8 bbl	Volume Recovered: none
Source of Release: Corrosion of load line ball valve and swage	Date and Hour of Occurrence: January 18, 2016	Date and Hour of Discovery: January 18, 2016 8:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Water truck driver arrived on location to find a hole in the drain valve of the load line of the produced water tank leaking into the bermed area.

Describe Area Affected and Cleanup Action Taken.\* The tank was drained and the valve and swage were replaced. Soil samples for BTEX, TPH via 8015 and chlorides will be collected and submitted following the spill and release guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Steve Moskal	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: <u>1/28/2016</u>	Expiration Date:
E-mail Address: steven.moskal@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: January 21, 2016 Phone: 505-326-9497	<u>Sample for BTEX, TPH, Chlorides</u>	

\* Attach Additional Sheets If Necessary

NUF1602830702

①