NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-16-15 Operator Chevron U.S.A. API #30-0 45-24503

Property Name USA Well No. 2 Location: Unit ___ Section 24 Township 32 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 76.3 Intermediate N/A Casing 33.2 Bradenhead 13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Int	Csg	INTERM Int	Csg
TIME 5 min	0	–	31.4		
10 min	0		30.9		
15 min	0		30.6		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Initial bradenhead was a puff to nothing.

By Lucinda Padilla

Witness ___

Calder Services.
(Position)

E-mail address lucinda.p@calderservices.com

OIL CONS. DIV DIST. 3

DEC 28 2015