



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAR 16 2016

Date of Test 3-16-16 Operator Chevron API #30-0 39-22227

Property Name Fincon Lt Well No. 82A Location: Unit 23 Section 27 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 64 Intermediate NA Casing 66 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>61</u>		
10 min	<u>0</u>		<u>62</u>		
15 min	<u>0</u>		<u>63</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

dead at 5 seconds (nothing when opened)
after 5 min shut-in
well has lines - well producing before shut-in
5.165.

By [Signature]
Surface Specialist
(Position)

Witness [Signature]

E-mail address gjf@chevron.com