



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8.17.10 Operator ConocoPhillips API #30-0 39-26699

Property Name San Juan 28.7 Well No. 1339 Location: Unit Section 35 Township 28 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 120 Intermediate 45 Casing 120 Bradenhead 27

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	44.9	121	fumes	126
10 min	0	44.9	123	fumes	127
15 min	0	44.9	124	fumes	128
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	fumes
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0 RCVD AUG 17 '10

REMARKS: BH blew down to nothing in 3 seconds Intermediate had blow to medium blow at 1.37 minutes whistle at 2 min. fumes at 2.40 min. whisper w/ fumes at test of test.

By Robert Archuleta

Witness Monica Guadalupe

(Position)

E-mail address