



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-15-14 Operator Concor Hill API #30-0 45-34152
Property Name SS 32-844 Well No. 18 Location: Unit N Section 11 Township 31 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 135 Intermediate 137 Casing 136 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	138	138	59	121
10 min	0	139	138	55	114
15 min	0	140	139	51	108
20 min				48	102
25 min				45	96
30 min				43	92

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓
Surges		
Down to Nothing		DIST. 3
Nothing	✓	OIL CONS. DIV.
Gas		REVD MAY 15-14
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 118

REMARKS:

BH Nothing when opened
Inf. - Hard blow - Casing falling with int.
Shut in when pressure up

By Frank Amstutz

Witness

Monica Kuehling
Recent wellbore schematic
Gas analysis intermediate &
production casing

(Position)

E-mail address _____