



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District IIV3distric.htm](http://emrdr.state.nm.us/ocd/District%20IIV3distric.htm)

COPY

*Emailed
TO NMOCD
5/15/15*

OIL CONS. DIV DIST. 3

JUN 05 2015

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-24-15 Operator John Russell API #30-0 45-20770

Property Name Mtn Ute Com A Well No. 1 Location: Unit G Section 3 Township 31N Range 14W

Well Status (Shut-In or Producing) Initial PSI: Tubing 208 Intermediate N/A Casing 353 Bradenhead 172

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>		<u>353</u>		
10 min	<u>Ø</u>		<u>353</u>		
15 min	<u>Ø</u>		<u>354</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges	
Down to Nothing	
Nothing	
Gas <u>✓</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 22 INTERMEDIATE N/A

REMARKS:

No H₂S on 4 Gas monitor
Decrease in pressure since last test w/o GA
*Please See attached WBD & Gas Analysis per Loran A.

By Mike Hartzell
Lead lease operator
(Position)

Witness

Investigate source of gas
to ensure that groundwater
is not impacted.
MIC

E-mail address mike_hartzell@xtenergy.com

Submitted
Gas Analysis
WBD
6/2/15
by mail