



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-1-16 Operator Elm Ridge API #30-0 43-20494
Property Name Badland Flats Well No. 1 Location: Unit 24 Township 23 Range 2
Well Status(Shut-In or Producing) Initial PSI: Tubing 118 Intermediate N/A Casing Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>118</u>		
10 min	<u>0</u>		<u>118</u>		
15 min	<u>0</u>		<u>118</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
APR 01 2016

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Slim hole - vacuum when opened nothing
when opened after 5 min shut in

By Daniel Martinez

Witness Monica Trevino

(Position)

E-mail address