



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

APR 07 2016 BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-7-16 Operator Burlington Gas API #30-0 39-30670

Property Name SS 28-6 Ut Well No. 121N Location: Unit 14 Section 14 Township 28 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 133 Intermediate 0 Casing 138 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	138	0	139
10 min	0	0	138	0	139
15 min	0	0	139	0	139
20 min				0	139
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	☒
Nothing		
Gas	☒	☒
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 10

INTERMEDIATE 0

REMARKS:

BH - long puff to lead in 1 second. Nothing when
Int - light blow through needle valve 5 min 10 min
nothing when opened after 5 min shut in

By Joshua Walker

Witness Monica Kuchling cleared at 10 min

(Position)

Nothing when opened after
5 min shut in

E-mail address _____