



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 11 2016

Date of Test 11 APR 2016 Operator BP/DEVON API #30-0 39-29614

Property Name NEBU Well No. 966A Location: Unit P Section 34 Township 31 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 7 Intermediate N/A Casing 4 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min			4		
10 min			4		
15 min			4		
20 min				N/A	
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	N/A
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT

By Daniel Fuller

Witness John Bluford

(Signature)
(Position)

E-mail address _____