



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3
APR 26 2016

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-26-16 Operator Burlington Res API #30-0 39-23683
Property Name 5527-564 Well No. 848 Location: Unit 3 Section 3 Township 27 Range 5
Well Status(Shut-In or Producing) Initial PSI: Tubing 285 Intermediate 170 Casing 328 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	171	332	0	342
10 min	0	172	334	0	345
15 min	0	172	336	0	347
20 min				0	349
25 min				0	352
30 min				0	354

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH - Nothing when opened - Nothing
When opened after 5 min shut-in - Int - Hand is low
Eight blow at 5 min - Jumes at 9 min - 10 - clear at 13 min.

By M d f
Mso cop
(Position)

Witness Moscat 30 min
Gas analysis - well bore schematic
cut & prod. strings

E-mail address _____