



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

MAY 18 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/18/2016 Operator Lively API #30-0 39-20178

Property Name Lively Well No. 21 Location: Unit L Section 31 Township 27 Range 7

Well Status(~~Shut In~~ or Producing) Initial PSI: Tubing 81 Intermediate — Casing 299 Bradenhead 68

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	—	299		
10 min	0	—	299		
15 min	0	—	299		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	☒
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	☒
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 22 INTERMEDIATE —

REMARKS:

Bradenhead blew down to a slight blow in 35 seconds.
started making water at 4½ minutes, 10 gals per minute.
Took water and gas samples.

By Russell Benson

Witness Paul Wicks

ABUT - Lively Exp
(Position)

E-mail address Russbenson@live.com