



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3dstric.htm](http://emnrd.state.nm.us/ocd/District%20III/3dstric.htm)

OIL CONS. DIV DIST. 3

MAY 24 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/24/2016 Operator Burlington API #30-0 39-23871

Property Name Harrington Well No. 6 Location: Unit K Section 31 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 107 Intermediate NA Casing 113 Bradenhead 58

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>6</u>	<u>58</u>	<u>110</u>		
10 min	<u>6</u>		<u>105</u>		
15 min	<u>6</u>		<u>103</u>		
20 min	<u>5</u>		<u>105</u>		
25 min	<u>5</u>		<u>108</u>		
30 min	<u>5</u>		<u>110</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>X</u>	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	<u>X</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 54

INTERMEDIATE NA

REMARKS:

Tank depth at start 13", well cycled @ 3 minutes into test. BH flowed water for duration of test. Water sample collect. Tank depth at end of test 16.5", BH flowed ~ 7.26 bbl. Test through 1" fittings.

By Kevin Shaw

Witness Jonathan D. Kelly

(Position)

E-mail address _____