



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 24 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/24/2016 Operator Burlington API #30-0 39-30380

Property Name Lively Well No. 21N Location: Unit M Section 31 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 100 Intermediate NA Casing 142 Bradenhead 56.8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME	<u>0.2</u>		<u>151</u>		
5 min	<u>0.1</u>		<u>157</u>		
10 min	<u>0.1</u>		<u>160</u>		
15 min	<u>0.1</u>		<u>162</u>		
20 min	<u>0.1</u>		<u>163</u>		
25 min	<u>0.1</u>		<u>164</u>		
30 min	<u>0.1</u>				

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges	<u>X</u>	
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	<u>X</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 31

INTERMEDIATE NA

REMARKS:

Well cycled prior to starting test, cycle end w/in first 5 min. BH flowed ~7 gals during test. Water sample collected. BH through 1/2" fittings.

By [Signature]

Witness [Signature]

(Position)

E-mail address _____