



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 25 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/25/2016 Operator COPC API #30-0 39-26694

Property Name San Juan 28-7 Well No. 225 Location: Unit B Section 34 Township 28 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 90 Intermediate 0 Casing 92 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	92	0	94
10 min	0	0	93	0	94
15 min	0	0	93	0	94
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Nothing on bradenhead. Intermediate blew down in
10 seconds

By _____

Witness Paul Walker

(Position)

MSO conocophillips

E-mail address _____