



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 25 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/25/2016 Operator COPC API #30-0 39-30663

Property Name San Juan 28-7 Well No. 13/N Location: Unit C Section 34 Township 28 Range 7

Well Status (Shut In or Producing) Initial PSI: Tubing 115 Intermediate 0.6 Casing 122 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
TIME		Int	Csg	Int	Csg
5 min	0	0.6	122	0	122
10 min	0	0.6	122	0	122
15 min	0	0.6	122	0	122
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

nothing on bradenhead Intermediate blew down to
nothing in 5 sec.

By _____

Witness Paul Wiebe

Angie E. MSO conocophillips
(Position)

E-mail address _____