



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

MAY 31 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/31/2016 Operator Chevron API #30-0 45-24392

Property Name Cardon Com SWD Well No. 1 Location: Unit A Section 27 Township 32 Range 13

Well Status(^{SWD}Shut-In or Producing) Initial PSI: Tubing 500 Intermediate 30 Casing 0 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	30	0	0	0
10 min	0	30	0	0	0
15 min	0	30	0	0	0
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Just a puff on bradenhead Intermediate blew down in 3 sec.

By W S M CVX
(Position)

Witness Paul Wiche

E-mail address _____