



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

JUN 01 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-1-2016 Operator ConocoPhillips API #30-0 39-20267

Property Name Carson SRC Well No. 1 Location: Unit L Section 1 Township 30 Range 5

Well Status (~~Shut In~~ or Producing) Initial PSI: Tubing 162 Intermediate NA Casing 180 Bradenhead 25

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>ST</u>	<u>NA</u>	<u>183</u>		
10 min	<u>-</u>	<u>NA</u>	<u>184</u>		
15 min	<u>-</u>	<u>NA</u>	<u>185</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>X</u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u>X</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 3 INTERMEDIATE

REMARKS:

Hard blow to steady flow on BH when opened. Steady flow after first
5 min. light blow for next 5 min of test. light Blow for last 5 min of test,
3psi on BH after five minute shut in.

By Brian Cain
MSO
(Position)

Witness [Signature] MSOCD

E-mail address