



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3
JUN 06 2016

Date of Test 6-6-2016 Operator ConocoPhillips API #30-039-21661

Property Name Sandra 28-7 Unit Well No. 236 Location: Unit H Section 6 Township 27 Range 7

Well Status (~~Shut In~~ or Producing) Initial PSI: Tubing 140 Intermediate 0 Casing 142 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	-	Ø	142	-	108
10 min	-	Ø	143	-	116
15 min	-	Ø	143	-	124
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X Puff
Nothing	X Puff.
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Opsi. INTERMEDIATE Opsi.

REMARKS:

Slight puff to nothing on BH when opened. Opsi on BH after 5 min shut in.
Slight puff to nothing on Intermediate when opened. Plunger came up at beginning
of intermediate test. Opsi on intermediate after 5 min. shut in.

By Jennifer D Bickley
MSO
(Position)

Witness J K H NMOC

E-mail address _____