



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3
JUN 06 2016

Date of Test 6-6-2016 Operator Copco Phillips Co API # 30-039-25802

Property Name San Juan 287 Well Well No. 249M Location: Unit 0 Section 30 Township 28 Range 7

Well Status (~~Shut In~~ or Producing) Initial PSI: Tubing 82 Intermediate 0 Casing 95 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	-	0	94	-	92
10 min	-	0	92	-	92
15 min	-	0	92	-	92
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X puff
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Opsi.

INTERMEDIATE Opsi.

REMARKS:

Slight puff to nothing on BH when opened. Opsi on BH after 5 min shut in.
Puff to nothing on intermediate when opened. Opsi on intermediate after 5 min shut in.

By Jennifer Reidley

Witness Jkh NMOC

(Position)

E-mail address _____