



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/DistrictOffices.htm>

OIL CONS. DIV DIST. 9

JUN 08 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-8-2016 Operator Robert L Bayless Pro. API #30-039-20110

Property Name Rockhouse Canyon Well No. 1 Location: Unit E Section 11 Township 24 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 14 Intermediate NA Casing 14 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>—</u>	<u>NA</u>	<u>14</u>		
10 min	<u>—</u>	<u>—</u>	<u>13</u>		
15 min	<u>—</u>	<u>—</u>	<u>13</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 psi INTERMEDIATE —

REMARKS:

Nothing on BH when opened. Opsi on BH after 5 minute shut in.
Nothing when opened.

By Robert L Bayless

Witness JKL NMOC

(Position)

E-mail address —