



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

JUN 10 2016

(submit 1 copy to above address)

Date of Test 6-10-16 Operator Crane Phillips API #30-0 39-07444

Property Name 5528-7 W Well No. 55 Location: Unit Section 12 Township 28 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 92 Intermediate 0 Casing 94 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0	0	95	0	97
10 min	0	0	96	0	97
15 min	0	0	96	0	97
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH- nothing when opened. Nothing when opened after 5 min shut in. Int- Puff when opened. Nothing when opened after 5 min shut in.

By Frank Conith M.S.O
(Position)

Witness Monica Kuehl
this well sets by a pond.

E-mail address