



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distr.htm](http://emnrd.state.nm.us/ocd/District%20III/3distr.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

JUN 14 2016

(submit 1 copy to above address)

Date of Test 6-14-16 Operator Burlington API #30-0 45-29936
Property Name Dasaly Well No. 2 Location: Unit 22 Township 30 Range 11
Well Status(Shut-In or Producing) Initial PSI: Tubing 840 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	0	0	0
10 min	0	0	0	0	0
15 min	0	0	0	0	0
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>✓</u>	<u>✓</u>
Nothing	<u>✓</u>	
Gas	<u>✓</u>	<u>✓</u>
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

PH Puff when opened. Nothing when opened after
5 min shut in. Int. light blow to clear at 15 Deconcs.

By Billy Gunnell

Witness _____

SWD M450
(Position)

Nothing after 5 min shut in

E-mail address billy.gunnell@cop.com