



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT
OIL CONS. DIV DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District III3district.htm](http://emrmd.state.nm.us/ocd/District%20III3district.htm)

JUN 16 2016

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

MAY 04 2016

(submit 1 copy to above address)

Date of Test 5/4/2016 Operator Turner Production API #30-0 39-2311

Property Name Turner 26 Well No. 1 Location: Unit I Section 26 Township 26 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 100 Intermediate — Casing 138 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	—	138		
10 min	0	—	138		
15 min	0	—	138		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Nothing on bradenhead

By Glenn R. Hise
Base Operator
(Position)

Witness Paul Wische

E-mail address glenn.hise@wqartisu.com