



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

DEC 18 2015

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12/26/15 Operator BP America Production Company API # 3004526206

Property Name GCU 178E-DK Location: Unit H Section 4 Township 27 Range 12
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 47 Intermediate - Casing - Bradenhead 88

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	-				Steady Flow	
10 minutes	0	-				Surges	
15 minutes	0	-				Down to Nothing	
20 minutes						No Flow	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	5	-				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ☐ Fresh ☐ Salty ☐ Sulfur ☐ Black ☐

5 Minute Shut-in Bradenhead 5 Intermediate -

REMARKS:

Blew from 1" valve. BH blew to a whisper in 2 sec.
unable to get casing sample and reading due to
cement

By Witness _____

(Position)