



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUN 23 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-23-16 Operator Burlington Res API #30-0 39-30418

Property Name Carson SRC Well No. 4E Location: Unit 2 Section 2 Township 30 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing 116 Intermediate 119 Casing 119 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	128	128	107	115
10 min	0	132	132	94	101
15 min	0	135	135	83	89
20 min				76	82
25 min				71	76
30 min				65	70

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 86

REMARKS:

BH Duff when opened - nothing when opened
after 5 min Shut-in Int. and had blow full 30
min test - production casing dropping with cut

By Brian Cain
MGO
(Position)

Witness Monica Kalding

E-mail address _____