



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-22-2016 Operator Redwolf Production API # 30-045-27124

Property Name Betta On Bisti 30 Well No. 9 Location: Unit I Section 30 Township 25 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing O Intermediate NA Casing O Bradenhead O

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BIH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	—	NA	O		
10 min	—		O		
15 min	—		O		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
JUN 22 2016

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE _____ BRADENHEAD Opsi INTERMEDIATE _____

REMARKS:

Well has been down for approx 4 months. Nothing on BH
when opened. Ops on BH after 5 min. Shut in.

By Bruce C. Delmont

Witness J K L NMCO

(Position)

E-mail address _____